

## Apollo GX55 Checklist (SAR Page)



### Activate SAR Map Function

1. Press Map Key
2. Turn “large knob” CCW three times
3. Press Grid smart key four times, until grid 4 shows
4. Turn “little knob” to select zoom

\*Note\* will only work when SAR Function is loaded; advanced checklist loads

### Grid Search (Parallel Line Search)

1. Press PAT Key
2. Parallel Line
3. Press Enter
4. Press SEL
5. Small Knob to adjust 1<sup>st</sup> Grid #
6. Large Knob to adjust 2<sup>nd</sup> & 3<sup>rd</sup> #
7. Press Enter
8. Press SEL
9. Large Knob to move cursor to spacing and direction
10. Small Knob to change reading
11. Press Enter
12. Large Knob CCW 1 click
13. Pat Key - Press

## Apollo GX55 Checklist (SAR Page)

### Creeping Line

1. Press SEL – INS flashes
2. Press Enter – Waypoint flashes
3. Press Enter
4. Turn “small knob” right/left to desired value
5. Turn “large knob” CW 1 click – Direction flashes
6. Turn “small knob” and “large knob” to desired dir
7. Press Enter
8. Turn “small knob” CW 1 click
9. Press SEL – 5.0 flashes
10. Turn “small knob” right/left to desired value
11. Press Enter

### Expanding Square (Based off of a User Waypoint)

1. Press SEL – INS flashes
2. Press Enter – waypoint type flashes
3. Press Direct TO
4. Press Enter – Spacing flashes
5. Turn “small knob” right/left to desire value
6. Turn “large knob” CW 1 click – direction flashes
7. Turn “small knob” & “large knob” to select the desired direction
8. Press Enter
9. Press Enter – To activate search pattern

### Mark Position (SAR Waypoint)

1. Press MRK smart key
2. Turn small & Large knobs to change name (SAR000 will be automatic)
3. Press Enter
4. Press DIRECT TO or NRST to fly to SAR Waypoint